5

10

15

a feed screw device are Both end parts of movably supported through cushioning members, and inertia force of the screw after a movable member moved by the screw has collided against a stopper is absorbed by a movement in an axial direction, so that an impact at a drive end can be softened. When the guide part comes into contact with the stopper and a projection lens barrel is positioned at an upper end of a moving stroke, an upward movement of the barrel is stopped, but a motor is in a rotating state. A driving power of the motor is continuously transmitted to the screw, but since upward movement of a nut member is restricted, a downward movement force is given from the motor to the screw. Then, the screw moves downward against an urging force of a spring.